

Production status of Test Gaps for RE4 RPCs in Upscope

***J. H. Bae, M. H. Kang, Y. K. Jeng, K. S. Lee,
S. Park, S. S. Shin, & J. Yoon @ KODEL***

Contents


- 1. Oil dirt on HPL surfaces**
- 2. Oiled layers**
- 3. Silk data for RE4/2 test gaps**
- 4. First HV data for RE4/2 test gaps**

1. Oil dirt on HPL surfaces


Checked that oil dirt remained on all the HPLs (all batches)

- Found that the stripe pattern created by the cleaning procedure was barely visible and just partially performed.
- At some places of the HPL sheets , the oil dirt still remained was thick.

Before cleaning



After cleaning by IPA only




After cleaning by thinner




2. Oiled layers

- Opened a RE4/2 test bottom gap (HPLs from batch 12)
- The bonding strength seems to be good enough, but the surface layer of the HPLs were easy detached like a stacked paper layer. (**HPLs are mechanically fragile !**)
 - > Phenol resin seems to be very poorly smeared into the craft papers.
 - Spacers were detached due to lack of the rigidity of the HPLs
- Places where the phenol resin was well smeared -> dark
Otherwise -> bright and having microscopic bright spots



- We expect that the oil pattern could be nicely formed only when the oil/heptane is well attached on the phenol-covered surface of the HPL.
- Bad condensation of the oil could be due to two different factors
 - 1) Oil dirt (microscopically thin layer remained even after cleaned by IPA and thinner)
(Still greasy even after cleaning by thinner & IPA)
 - 2) Poor condition of smeared phenol resin into the craft papers
(The color is brighter and having white microscopic spots)

Bad oiled patterns especially on the places that the phenol was poorly smeared.



Good oiled patterns on the places that the phenol was relatively well smeared.





Gap produced with new HPLs



Gap produced with old HPLs




Gap produced with old HPLs



Gap produced with old HPLs

3. Silk data for RE4/2 test gaps

- Mean value of the graphite surface resistivity
= **191.6 ± 26.0 (sigma) k Ω /square**
- The desirable value lies bet. **$50 \sim 200$ k Ω /square**
- The value seems to be ~ twice larger due to cold weather (the temperature ranged $10 \sim 15$ °C)
- The temperature was NOT well controlled during the January shutdown period.



	A	B	C	D	E	F	G
1	Bakelite Code	Production Number	Production Batch		B	TN	TW
2	1A12E111019010399	399	12		170		
3	1B12E111019010400	400	12		211		
4	1C12E111019010401	401	12		184		
5	1D12E111019010402	402	12		193		
6	1E12E111019010403	403	12		233		
7	2A12E111019010404	404	12		170		
8	2B12E111019010405	405	12		214		
9	2C12E111019010406	406	12				
10	2D12E111019010407	407	12		239		
11	2E12E111019010408	408	12		247		
12	3A12E111019010409	409	12		161		
13	3B12E111019010410	410	12		187		
14	3C12E111019010411	411	12		201		
15	3D12E111019010412	412	12		169		
16	3E12E111019010413	413	12		176		
17	4A12E111019010414	414	12		211		
18	4B12E111019010415	415	12		214		
19	4C12E111019010416	416	12		185		
20	4D12E111019010417	417	12		132		
21	4E12E111019010418	418	12		165		
22	5A12E111019010419	419	12		151		
23	5B12E111019010420	420	12		189		
24	5C12E111019010421	421	12		220		
25	5D12E111019010422	422	12				
26	5E12E111019010423	423	12		204		

27	6A12E111019010424		424	12			190	167
28	6B12E111019010425		425	12			197	201
29	6C12E111019010426		426	12			182	145
30	6D12E111019010427		427	12			211	186
31	6E12E111019010428		428	12			213	
32	7A12E111019010429		429	12			204	193
33	7B12E111019010430		430	12			207	137
34	7C12E111019010431		431	12			179	180
35	7D12E111019010432		432	12			205	202
36	7E12E111019010433		433	12			210	165
37	8A12E111019010434		434	12			185	136
38	8B12E111019010435		435	12			166	193
39	8C12E111019010436		436	12			149	199
40	8D12E111019010437		437	12			210	207
41	8E12E111019010438		438	12			195	168
42	9A12E111019010439		439	12			167	230
43	9B12E111019010440		440	12			195	220
44	9C12E111019010441		441	12			180	187
45	9D12E111019010442		442	12			213	213
46	9E12E111019010443		443	12			220	226
47	0A12E111019010444		444	12			215	201
48	0B12E111019010445		445	12			203	137
49	0C12E111019010446		446	12			202	145
50	0D12E111019010447		447	12			215	230
51	0E12E111019010448		448	12				195










4. First HV data for RE4/2 test gaps

- The first HV test for 10 RE4/2 test bottom gaps seems to be good.
- One gap was disconnected from HV cabling at somewhere -> drop it !
- All the rest 9 gaps were QC certified !
- At 6.0 kV, $i \sim 0.2 \mu\text{A}$ for all the gaps
At 10.0 kV, maximum $i = 0.74 \mu\text{A}$
 $i(120\text{h})/i(63\text{h}) < 1.0$ for all the gap
- But we expected the currents of the test gaps should be smaller than the normal gaps to be built with a right resistivity range !
(the resistivity of the HPLs in batch 12 is higher)
- The good HV test results for just 7 days results do not guarantee long-term stability without solving oil problem.

4. HV tests				$HV_0(293\text{ K}, 1013\text{ hPa}) = HV_{\text{applied}} \frac{1013\text{ hPa}}{P} \frac{T}{293\text{ K}}$					
	Starting date of test		Feb. 07, 2012		Total gas rate = /l/h		Gas	Mixture	
	Time from test start	Date/ Time	P (hPa)	T (°C)	HV_{applied} (kV)	HV_0 (kV)	I_{ini} (μA)	I_{final} (μA)	H (%)
	0.0 h	Feb. 07, 2012 / 19:00	1021.5	18	1	0.98	0.01	0	23
	0.5 h	19:30	1021.5	18	2	1.97	0.01	0.01	23
	1.0 h	20:00	1021.5	18	3	2.95	0.01	0	23
	1.5 h	20:30	1022.3	18	4	3.94	0.02	0.01	23
	2.0 h	21:00	1023.3	18	5	4.92	0.02	0.02	23
	2.5 h	21:30	1023.3	18	6.0 12 h test		5.9	0.02	0.02
	14.5 h	Feb. 08, 2012 / 09:30	1022.8	17	7	6.86	0.02	0.02	24
	15.0 h	10:00	1022.8	19	7.5	7.4	0.03	0.03	22
	15.5 h	10:30	1022.8	20	8	7.92	0.03	0.03	21
	16.0 h	11:00	1022.8	20	8.4	8.32	0.04	0.04	21
	16.5 h	11:30	1022.9	20	8.6	8.52	0.04	0.04	21
	17.0 h	12:00	1022.9	20	8.8	8.71	0.04	0.04	21
	17.5 h	12:30	1022.4	20	9	8.92	0.05	0.05	21
	18.0 h	13:00	1022.4	20	9.2	9.11	0.07	0.05	21
	18.5 h	13:30	1021.4	20	9.4	9.32	0.08	0.07	21
	19.0 h	14:00	1021.4	20	9.6	9.52	0.12	0.13	21
	19.5 h	14:30	1020.8	20	9.8	9.72	0.18	0.22	21
	20.0 h	15:00	1020.8	20	10	9.92	0.29	0.29	21
	21.0 h	16:00	1020.8	20	9.6	9.53	0.13	0.13	21
	24.0 h	19:00	1022.3	19			9.48	0.12	23
	39.0 h	Feb. 09, 2012 / 10:00	1027.9	18			9.4	0.09	23
	42.0 h	13:00	1026.1	20			9.48	0.09	21
	45.0 h	16:00	1025.5	20			9.48	0.1	21
	48.0 h	19:00	1024.9	19			9.46	0.09	22

QC decision	Current Limits at 6.0 kV	RE4/2 TW	RE4/2 TN	RE4/2 BT	$i(14.5\text{h})$ at 6.0 kV	Final Decision	Certified	O			
		1.5 μA	1.5 μA	1.5 μA	0.02						
		RE4/3 TW	RE4/3 TN	RE4/3 B							
	Current Limits at 10.0 kV	1.5 μA	1.5 μA	1.5 μA							
		RE4/2 TW	RE4/2 TN	RE4/2 B	0.29		Not certified	x			
		5.0 μA	5.0 μA	10.0 μA							
	Current Limits at 9.6 kV at t = 120 h	RE4/3 TW	RE4/3 TN	RE4/3 B	Criterion $i(120\text{h})/(63\text{h}) < 1.5$						
		5.0 μA	5.0 μA	10.0 μA							
		RE4/2 TW	RE4/2 TN	RE4/2 B	$i(63\text{h})$	0.08					
		2.0 μA	2.0 μA	3.5 μA	$i(120\text{h})$	0.06					
		2.0 μA	3.5 μA	5.0 μA	0.75						

Set at 10.0 kV at $t = 20.0$ h, and at 9.6 kV from 21 to 120 h for the long-term test.



5. Conclusion & discussions

1) Conclusions

- The condition for the oiled surfaces looks too poor compared to the previous gaps produced in the old production.
- Cleaning thinner & IPA is NOT a right solution for the delivered HPLs.
- The cleaning procedure might not properly done for the current HPL delivered on the last December.
For the next HPLs to be delivered to KODEL, we ask the same cleaning process done for the old HPLs used in the previous gap production.
- The surface resistivity should be in a range from 50 to 200 kOhm/square.
-> Temperature control problem will be fixed.

2) Discussions

- What do we do for the other HPLs to be used for the gap production ?